

Porsche Carrera Cup France 2022

Note Technique 06/2022

Chers tous,

Veillez trouver ci-dessous la note technique 06/2022 applicable à votre Porsche 992 GT3 Cup. Nous restons à votre disposition si vous avez des questions.

SERRAGE DES DURITES DE FREIN ARRIERES

Porsche Motorsport vous informe que le couple de serrage des 4 raccords rigides de durites de frein arrières doit être contrôlé et, si nécessaire, re-serré au couple de 14 N.m avant toute future utilisation sur circuit de votre Porsche 992 GT3 Cup.

Le couple des raccords vissés doit être contrôlé tout en immobilisant la pièce centrale avec la clé correspondante. Ces pièces de raccordement sont situées entre le réservoir de carburant et la cloison avant.

TIGHTENING REAR BRAKE LINES

Porsche Motorsport informs that the torque of the 4 pipe fittings on the rear brake lines MUST be checked and, if necessary, tightened to a torque of 14 Nm before the Porsche 911 GT3 Cup (992) is used for any further track activities.

The torque on the outer nipples should be checked while the centre connection part is countered using the correct spanner. The connection parts are located between the fuel cell and front bulkhead.

