

# Porsche Carrera Cup France 2022

## Note Technique 11/2022


Chers tous,

Veillez trouver ci-dessous la note technique 11/2022 applicable à votre Porsche 992 GT3 Cup. Nous restons à votre disposition si vous avez des questions.

### ROULEMENT A ROULEAUX CYLINDRIQUES BV

Porsche Motorsport vous informe que sur toutes les Porsche 992 GT3 Cup, le roulement à rouleaux cylindriques d'arbre secondaire (pos. 8) situés derrière le roulement 4-points, doit être changé par la nouvelle version lors de votre prochaine révision BV.

Cette nouvelle version confère une meilleure tenue dans le temps. La durée de vie maximale du roulement reste toutefois de 60h, ce qui correspond à l'intervalle habituel de révision BV.




#### Liste de pièces :

Ancienne ref.	Nouvelle ref.	Description	Qté par BV
9F1.311.440.A	9F1.311.440	Roulement à rouleaux cylindriques	1

## GEARBOX CYLINDRICAL ROLLER BEARING

Porsche Motorsport informs that on all type Porsche 911 GT3 Cup (992) cars, the pinion shaft cylindrical roller bearing (8), behind the four-point bearing, must be changed for a new version during the next gearbox rebuild. The new version has improved long-term durability. The maximum permitted runtime for the bearing remains 60 hours (corresponds with a standard rebuild interval).



**Parts list :**

Part number (old)	Part number (new)	Description	Qty per car
9F1.311.440.A	9F1.311.440	Cylindrical roller bearing	1