

Porsche Carrera Cup France 2021

Note Technique 15/2021

Chers tous,

Veillez trouver ci-dessous la note technique 15/2021 applicable à votre Porsche 992 GT3 Cup. Nous restons à votre disposition si vous avez des questions.

MAITRE CYLINDRE DE FREIN

Porsche Motorsport vous informe que si vous utilisez votre Porsche 992 GT3 Cup avec le système ABS (hors PCCF), une usure accentuée des maitres-cylindres de frein pourra être constatée. Il est ainsi recommandé de contrôler chaque maitre-cylindre régulièrement et de remplacer les composants usés dès que nécessaire ou à chaque 2500 km

Un kit de révision est disponible pour chaque maitre-cylindre via la plateforme de vente de pièces détachées motorsport.

Kit de révision	Pour MC de frein AV (19.1mm)	9F1.698.310.B
	Pour MC de frein AR (15.9mm)	9F1.698.310.C

BRAKE MASTER CYLINDER

Porsche Motorsport informs that when operating the Porsche 911 GT3 Cup (992) with ABS-system fitted (outside PCCF), increased wear to the brake master cylinders can be observed. It is therefore recommended that both brake master cylinders are checked on a regular basis and the worn parts are replaced when necessary or after 2,500 km latest.

Repair kits are available for both brake master cylinders via spare parts sales.

Repair kit	For brake master cylinder FA (19.1mm)	9F1.698.310.B
	For brake master cylinder RA (15.9mm)	9F1.698.310.C