

Porsche Carrera Cup France 2021

Note Technique 16/2021

Chers tous,

Veillez trouver ci-dessous la note technique 16/2021 applicable à votre Porsche 992 GT3 Cup. Nous restons à votre disposition si vous avez des questions.

DEMI-BERCEAUX ARRIERES

Porsche Motorsport vous informe que tous les demi-berceaux arrières de Porsche 992 GT3 Cup doivent être remplacés avant leur prochaine utilisation. Tous les engagés PCCF ont réceptionné la nouvelle version de demi-berceau arrière (9F1.505.063.**B** et 9F1.505.064.**B**) gratuitement sur la manche de Monza.

Les versions de demi-berceaux sans indice (9F1.505.063 et 9F1.505.064) doivent être détruites, quel que soit leur kilométrage et ne doivent plus être utilisées.

Version	Ancienne	Nouvelle
Demi-berceau G	9F1.505.063	9F1.505.063.B
Demi-berceau D	9F1.505.064	9F1.505.064.B

REAR SIDE SECTION

Porsche Motorsport informs that all rear side sections on the Porsche 911 GT3 Cup (992) must be replaced prior to the next event. All customers will be provided with new rear side sections (9F1.505.063.**B** and 9F1.505.064.**B**) free of charge.

Rear side sections without index (9F1.505.063 and 9F1.505.064) must be scrapped, regardless of the mileage completed and must no longer be used.

Version	Old	New
LEFT rear side section	9F1.505.063	9F1.505.063.B
RIGHT rear side section	9F1.505.064	9F1.505.064.B